

序号	报告编号	发布日期	结论	影像资料
269	GX-B1364/22-A-25769	2025/7/21	所检项目合格。	 <p>The photograph shows two individuals in white lab coats, likely technicians, inspecting a piece of industrial equipment. One person is looking at a control panel on the right, which features a digital display and several analog gauges. The other person is standing next to a large, dark-colored cabinet or door. A timestamp '2025.07.17' is visible in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
270	GX-B1364/22-A-25770	2025/7/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
271	GX-B1364/22-A-25771	2025/7/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
272	GX-B1364/22-A-25772	2025/7/21	所检项目合格。	 A photograph showing two technicians in white uniforms with a blue logo on the back, standing in an industrial environment. They are positioned in front of a large black control panel or machine. The technician on the right is looking at a control panel with a screen and several analog gauges. The technician on the left is looking towards the same area. The background includes a grey metal cabinet and a red structure. A timestamp '2025.07.17' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
273	GX-B1364/22-A-25773	2025/7/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
274	GX-B1364/22-A-25774	2025/7/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
275	GX-B1364/22-A-25775	2025/7/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
276	GX-B1364/22-A-25776	2025/7/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
277	GX-B1364/22-A-25777	2025/7/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
278	GX-B1364/22-A-25778	2025/7/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
279	GX-B1364/22-A-25779	2025/7/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
280	GX-B1364/22-A-25785	2025/7/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
281	GX-B1364/22-A-25780	2025/7/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
282	GX-B1364/22-A-25781	2025/7/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
283	GX-B1364/22-A-25782	2025/7/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
284	GX-B1364/22-A-25783	2025/7/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
285	GX-B1364/22-A-25784	2025/7/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
286	GX-B1364/22-A-25761	2025/7/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
287	GX-B1364/22-A-25762	2025/7/22	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
288	GX-B1364/22-A-25763	2025/7/22	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
289	GX-B1364/22-A-25764	2025/7/22	所检项目合格。	 <p>The photograph shows two men in light blue work shirts standing in front of a large, dark-colored industrial machine. The man on the left is wearing glasses and looking towards the machine. The man on the right is looking at a control panel on the right side of the machine. The control panel features a digital display and several analog gauges. A red date stamp '2025.07.16' is visible in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
290	GX-B1364/22-A-25765	2025/7/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
291	GX-B1364/22-A-25766	2025/7/22	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
292	GX-B1364/22-A-25767	2025/7/22	所检项目合格。	


序号	报告编号	发布日期	结论	影像资料
293	GX-B1364/22-A-25768	2025/7/22	成束电线电缆燃烧试验不合格；其余所检项目合格。	


序号	报告编号	发布日期	结论	影像资料
294	GX-B1363/22-A-25400	2025/7/22	所检项目合格。	 A photograph showing two men in white short-sleeved shirts and dark trousers inspecting a large, industrial-looking machine. The machine has a prominent metal hood or chimney structure on top. One man is on the left, looking into the machine's open compartment, while the other is on the right, also looking in. The background shows a window with a view of greenery outside. A date stamp '2025.07.17' is visible in the bottom right corner of the photo.


序号	报告编号	发布日期	结论	影像资料
295	GX-B1363/22-A-25401	2025/7/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
296	GX-B1363/22-A-25402	2025/7/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
297	GX-B1363/22-A-25403	2025/7/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
298	GX-B1458/22-A-25016	2025/7/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
299	GX-B1458/22-A-25017	2025/7/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
300	GX-B1458/22-A-25018	2025/7/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
301	GX-B1458/22-A-25019	2025/7/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
302	GX-B1613/23-A-25002	2025/7/25	所检项目合格。	


序号	报告编号	发布日期	结论	影像资料
303	GX-B1364/22-A-25788	2025/7/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
304	GX-B1364/22-A-25786	2025/7/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
305	GX-B1364/22-A-25787	2025/7/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
306	GX-B1365/25-A-25066	2025/7/25	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
307	GX-B1366/25-A-25081	2025/7/25	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
308	GX-B1367/20-A-25056	2025/7/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
309	GX-B1363/22-A-25404	2025/7/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
310	GX-B1363/22-A-25405	2025/7/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
311	GX-B1363/22-A-25406	2025/7/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
312	GX-B1363/22-A-25413	2025/7/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
313	GX-B1364/22-A-25789	2025/7/29	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
314	GX-B1509/20-A-25036	2025/7/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
315	GX-B1509/20-A-25037	2025/7/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
316	GX-B1363/22-A-25399	2025/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
317	GX-B1363/22-A-25409	2025/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
318	GX-B1363/22-A-25410	2025/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
319	GX-B1363/22-A-25411	2025/7/28	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
320	GX-B1363/22-A-25412	2025/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
321	GX-B1509/20-A-25035	2025/7/25	所检项目合格。	 <p>The photograph shows two individuals in light blue lab coats working in a laboratory or workshop. They are positioned at a workbench with a white top and blue base. One person is holding a multimeter, and the other is looking at a component on the bench. A yellow mat is visible on the workbench. The background features white shelving units. A timestamp '2025.07.22' is visible in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
322	GX-B1364/22-A-25790	2025/7/29	所检项目合格。	 A photograph showing two technicians in white uniforms inspecting a large industrial machine. The technician on the left is looking towards the machine, while the one on the right is looking at a control panel. The date '2025.07.28' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
323	GX-B1364/22-A-25791	2025/7/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
324	GX-B1365/25-A-25068	2025/7/29	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
325	GX-B1366/25-A-25083	2025/7/29	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
326	GX-B1363/22-A-25408	2025/7/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
327	GX-B1363/22-A-25407	2025/7/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
328	GX-B1458/22-A-25022	2025/7/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
329	GX-B1458/22-A-25021	2025/7/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
330	GX-B1458/22-A-25020	2025/7/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
331	GX-B1367/22-A-25058	2025/7/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
332	GX-B1367/22-A-25057	2025/7/29	所检项目合格。	 <p>The photograph shows two individuals in a laboratory or workshop environment. They are wearing light blue short-sleeved shirts with a logo on the back. One person is using a multimeter to test a component on a workbench. The workbench has various tools and equipment. A date stamp '2025.07.26' is visible in the bottom right corner of the image.</p>